

Damage to Property by DUMBO MOVING


Parties responsible:

DUMBO MOVING, Anthony Collazo – claims manager

TCE Insurance, Noelle Defede *NAIC # 16698933*

Private Insurance, Rommel Aquino

Condition of the property as of June 6th,
when the hallway was cleaned, cleared and photographed
in advance of the move date on June 8th.



June 6th




June 9th

Massive gash in the wall by the 2nd
floor apartment door. The DUMBO
MOVERS must come down the
winding staircase past the 2nd floor
apartment door to move items from
the 3rd floor apartment to the truck
outside of the building.

Further evidence of the damage caused by DUMBO MOVERS on June 8th.



June 6th



June 9th

Massive abrasions to the underside (ceiling) of the stairwell by the 2nd floor apartment. The DUMBO MOVERS must come down the winding staircase past the 2nd floor apartment to move items from the 3rd floor apartment to the truck outside of the building.

Further evidence of the damage caused by DUMBO MOVERS on June 8th.



June 6th



June 9th

Massive abrasions to the 3rd floor apartment door. The door opens into the apartment and the DUMBO MOVERS would carry things through the threshold and leave the evidenced damage on the door.

Further evidence of the damage caused by DUMBO MOVERS on June 8th.



June 6th



June 9th

Massive abrasions to the custom tile wall by the 2nd floor apartment. The DUMBO MOVERS would come down the stairwell and pass by the custom tile wall to move items to the truck.

Further evidence of the damage caused by DUMBO MOVERS on June 8th.




June 6th




June 9th

Massive abrasions and gashes in the built-in picture shelf along the entry landing wall. The DUMBO MOVERS would pass through the entry landing to move items from the 3rd floor to the truck.

Further evidence of the damage caused by DUMBO MOVERS on June 8th to the hard wood floors.



June 6th



June 9th

Additional evidence of the damage caused by DUMBO MOVERS on June 8th.

